



# Certificate of Inspection

PIPA Device Reference Number: **33721** | Tag Number: **33721** | Report: **434559-v1**

## Pass with advisories

I confirm that this inflatable castle device has been inspected in accordance with the PIPA scheme rules, and where it is applicable, it meets the requirements of BS EN 14960. All details contained within this inspection report are a true representation of what I found and observed during my inspection process.

Expiry Date:  
**24 March 2027**

Inspector Name: **Clive Ellis**  
Inspection Body: **Essex Inflatables**  
Inspection Report ID: **434559-v1**  
Signature:

## Device Details

Manufacturer: **Outstone Inflatables**

Device Type: **Castle**

Manufactured Date: **Unknown**

Device Description:

Device Disclaimer: I confirm that this inflatable castle device has been inspected in accordance with the PIPA scheme rules, and where it is applicable, it meets the requirements of BS EN 14960. All details contained within this inspection report are a true representation of what I found and observed during my inspection process.

Dimensions (L x W x H): **4.8m x 3.8m x 3.2m**

Tested for Indoor Use Only? **No**



### View Report

Scan the QR Code to access the full report

